

RECEIVING INSPECTION REPORT

Approved For Release 2000/04/18 : CIA-RDP81B00879R000500080047-2

No. 11552

RECEIVED FROM

PLATE 19

DATE REC'D. 3-14-57

P.O. NO.

VENDOR PACKING SLIP NO.

CHARGE TO QUANTITY RECEIVED	CONTRACT CODE NO.	DRAWING NUMBER	DWG. BASED ON STANDARD PART NO.	DWG. REV.	LOT NO.	CLASS NUMBER	QTY. NUMBER	BUY OUT CODE NO.	ACCT. OR W.O. NO.	REMARKS
3	322	C	124	C	10					
DRAWING NO. AND DESCRIPTION										QUANTITY
										ACCEPTED
731192-B Cover Camera										3 ✓
IPB 100752										

RECEIVED
BYINSPECTED
BY

DATE

REJECTS RETURNED
ON SHIP MEMO NO.

RECEIVING INSPECTION REPORT

HYCON MFG. COMPANY

2961 E. COLORADO ST., PASADENA, CALIF.

No. 11612

RECEIVED FROM

PLATE 19

DATE REC'D. 3-14-57

P.O. NO.

VENDOR PACKING SLIP NO.

CHARGE TO QUANTITY RECEIVED	CONTRACT CODE NO.	DRAWING NUMBER	DWG. BASED ON STANDARD PART NO.	DWG. REV.	LOT NO.	CLASS NUMBER	QTY. NUMBER	BUY OUT CODE NO.	ACCT. OR W.O. NO.	REMARKS
20	322	C	100	C	13					
DRAWING NO. AND DESCRIPTION										QUANTITY
										ACCEPTED
731903-A -pucar 150 count										20 ✓
IPB 102767										

RECEIVED
BYINSPECTED
BY

DATE

REJECTS RETURNED
ON SHIP MEMO NO.

Approved For Release 2000/04/18 : CIA-RDP81B00879R000500080047-2